

REHABILITATION OF BEAR BRAND NO. 2 RESERVOIR



Bear Brand Reservoir Exterior Containment Prior to Coating

PROJECT LOCATION:

Laguna Niguel

PROJECT SCOPE:

Work at the Bear Brand No. 2 Reservoir includes: structural and corrosion repairs, tank operation and safety improvements (including spiral stairways, full perimeter guardrails, and interior fiberglass platform and ladders), installation of a cathodic protection system, and re-coating of the interior and exterior of the reservoir.

Construction documents for the Bear Brand No. 2 Reservoir Rehabilitation project were prepared by Harper & Associates.



Interior Structural Improvements

PROJECT DETAILS:

- Contract Award – 01/17/2019
- Construction Amount - \$756,300
- Percentage Constructed - 80%
- Estimated Completion - December 2019

NOTES:

Work continues on interior coating. Structural repairs near completion.



Interior Coating Spark Test Being Performed